

## 4x79 Quick Start Guide

- 1) **Check load cells:** Check that the load cells are mounted mechanically correct.
- 2) **Check electrical connections:** Check supply voltage, load cells, digital I/O and analog interface.
- 3) **Connect voltage:** Check that the software indication during the power up sequence matches the program name on the front page of the supplied user manual.
- 4) **Unlock parameters:** Press **[F]** until **PASS** shows in the display. Press **[↑]** / **[↓]** until the correct password (**1357**) appears. Press **[↵]** to confirm.
- 5) **Configure the number of supporting points:** Press **[F]** until the display shows **n.Crn..** Press **[↑]** / **[↓]** until the correct number of supporting points is shown. Press **[↵]** to confirm. If it is necessary to change these parameters, the power should be turned off and on again.
- 6) **Power off/on and check load cells:** Check that both **TXBB** lamps are green. Check that the **TXLC** lamp is yellow. Check that the **1** to **X** lamps are OFF.
- 7) **Unlock parameters again:** Enter the correct password (1357) in the **PASS** parameter.
- 8) **Configure weight unit:** Press **[F]** until **Unit** shows in the display. Adjust with **[↑]** / **[↓]**. Press **[↵]** to confirm. Options: kilograms (**kg.**), pounds (**Lb.**), grams (**gr.**) and tons (**t.**).
- 9) **Configure the decimal point position:** Press **[F]** until **dPno** shows in the display. Press **[↑]** / **[↑]** until the desired value appears. Press **[↵]** to confirm. Note that the total capacity of the weighing system should reflect the setting.
- 10) **Configure the resolution:** Press **[F]** until **div** shows in the display. Press **[↑]** / **[↑]** until the desired value appears. Press **[↵]** to confirm. Options: **0,001** - **0,002** - **0,005** - **0,010** - ... (in kg, Lb., gr. or t.).
- 11) **Configure the analog output:** Indicate the load for 20 mA output signal (usually the total load cell capacity). Press **[F]** until **An.SP.** shows in the display. Press **[↑]** / **[↑]** until the desired value appears. Press **[↵]** to confirm.
- 12) **Configure output signal during error situations:** Indicate the value on the analog output during error situations (normally 20.00 mA). Press **[F]** until **An.Err.** shows in the display. Press **[↑]** / **[↑]** until the desired value appears. Press **[↵]** to confirm.
- 13) **Perform zero:** Press and hold down **[F]**. Then press **[Esc]** to return to **LoAd** indication. Press **[F]** until **Zero** shows in the display. Press **[↵]** to zero.
- 14) **Return to weight indication:** Press and hold down **[F]**. Then press **[Esc]** to return to **LoAd** indication.
- 15) **Lock parameters:** Press **[F]** until **PASS** shows in the display. Press **[↓]** until **0** shows in the display. Press **[↵]** to confirm.



Please refer to the accompanying user manual for additional information regarding electrical connection, DIP switch settings including measurement time and filtering, general operation, calibration, weight control, analog transfer to PLC/control system, Ethernet functionality and troubleshooting.